
WRB 120 MQ-10-0.6 Glass fiber optic



- High-quality glass fibres
- Resistant to high temperature
- Robust, highly flexible






Safety instructions

The Instruments are not to be used for safety applications, in particular applications in which safety of persons depends on proper operation of the instruments.

These instruments shall exclusively be used by qualified personnel.



reflective sensor design n 6 mm
n
6 mm
mm
tube-Ø
+ 180 °C (short-term up to +300 °C)
er for glass fiber optics
nsor probe) bre (Fibre)
fi er