


04/14 IL014004ZU

EWK-03...
EWK-05...
EWK-08...
EWK-10...

 **IP 43**



 **(en) Electric current! Danger to life!**

Only skilled or instructed persons may carry out the following operations.

(de) Lebensgefahr durch elektrischen Strom!

Nur Elektrofachkräfte und elektrotechnisch unterwiesene Personen dürfen die im Folgenden beschriebenen Arbeiten ausführen.

(fr) Tension électrique dangereuse!

Seules les personnes qualifiées et averties doivent exécuter les travaux ci-après.

(es) ¡Corriente eléctrica! ¡Peligro de muerte!

El trabajo a continuación descrito debe ser realizado por personas cualificadas y advertidas.

(it) Tensione elettrica: Pericolo di morte!




Solo persone abilitate e qualificate possono eseguire le operazioni di seguito riportate.

(zh) 触电危险!


只允许专业人员和受过专业训练的人员进行下列工作。

(ru) Электрический ток! Опасно для жизни!


Только специалисты или проинструктированные лица могут выполнять следующие операции.





Pos.		EWK-...
1		4x




Type	B mm	H mm	B1 mm	H1 mm	B2 mm	H2 mm	Pv W*
EWK-03051	301	502	275	535	181	333	21
EWK-05051	551	502	525	535	431	333	35
EWK-08051	801	502	775	535	681	333	49
EWK-10051	1051	502	1025	535	931	333	62
EWK-03061	301	652	275	685	181	483	26
EWK-05061	551	652	525	685	431	483	41
EWK-08061	801	652	775	685	681	483	57
EWK-10061	1051	652	1025	685	931	483	70
EWK-03081	301	802	275	835	181	633	32
EWK-05081	551	802	525	835	431	633	47
EWK-08081	801	802	775	835	681	633	67
EWK-10081	1051	802	1025	835	931	633	84
EWK-03091	301	952	275	985	181	783	36
EWK-05091	551	952	525	985	431	783	55
EWK-08091	801	952	775	985	681	783	73
EWK-10091	1051	952	1025	985	931	783	99




* 35° / 55° = Δ 20K




1 A




2 A



3 A




4 A




Accessories

Pos.		EW-GBS
1		4x
2		4x


1 B




2 B




3 B







1 A




1 B





1





2






3






1



2



Accessories

Pos.	EWS-HG	
1		1x
2		1x
3		1x
4		1x
5		2x
6		2x
7		1x
8		1x








Diagram illustrating the assembly of the door handle components (2 through 15) onto the door plate (1) and the door edge (16). The components are numbered 2 through 15, and the assembly steps are indicated by arrows and numbers in boxes.

- Component 2:** DIN 7981 4,2 x 38 screw.
- Component 3:** DIN 7981 4,0 x 25 screw.
- Component 4:** M6 x 16 screw.
- Component 5:** DIN 7981 4,2 x 38 screw.
- Component 6:** DIN 7981 4,0 x 25 screw.
- Component 7:** M6 x 16 screw.
- Component 11:** DIN 7981 4,2 x 38 screw.
- Component 12:** DIN 7981 4,0 x 25 screw.
- Component 13:** DIN 7981 4,2 x 38 screw.
- Component 14:** DIN 7981 4,2 x 38 screw.
- Component 15:** M6 x 16 screw.

The assembly steps are indicated by arrows and numbers in boxes:

- Step 13: Install component 13 into the door plate (1).
- Step 14: Install component 14 into the door plate (1).
- Step 11: Install component 11 into the door plate (1).
- Step 12: Install component 12 into the door plate (1).
- Step 6: Install component 6 into the door plate (1).
- Step 3: Install component 3 into the door plate (1).
- Step 5: Install component 5 into the door plate (1).
- Step 2: Install component 2 into the door plate (1).
- Step 4: Install component 4 into the door plate (1).
- Step 7: Install component 7 into the door plate (1).

Technical drawing of a door handle assembly. The main view shows a side profile of the handle, which is a long, curved lever with a circular grip. It is mounted on a rectangular base plate. A small circular detail shows the mounting bracket and the handle's attachment point. A small inset shows a detail of the mounting bracket's internal structure.

