

( (

## **Model Number**


## OMH-RL28-C


Weld slag cover model


## **Features**

- · Protection from welding beads
- Simple and fast mounting

## **Dimensions**







# **Technical data**


Accessories provided	glass M4 x 8 mm thumb screw
Mechanical specifications	
Material	
Housing	Metal sheet (steel), black-coated
Optical face	glass
Suitable series	
Series	RL28

# Mounting

## Step 1

- Push lens into the lip on the housing as shown.
- Rotate lens into position as shown.

Caution: Glass lens is fragile, handle with care



## Step 2

After lens has been rotated into it's correct position. Secure it as shown below. Caution: Do not over tighten, glass lens is very fragile.



www.pepperl-fuchs.com