




Dimensions



Model Number

MH 01-M30

Mounting brackets for sensors

Features


- Suitable for M30 sensors
- Simple and fast mounting

Technical data

Mechanical specifications

Material	Clamping cylinder: Diecast zinc Support bracket: Steel
Note	rod not included

Installation instructions



- ① Fasten the two parts of the mounting clamp (a) loosely by means of the screw (b) and the nut (c) supplied.
- ② Attach the mounting bracket (d) and then tighten the screw (b) in such a way that the bracket can still be turned.
- ③ Tighten the screw fully after the sensor has been mounted and aligned.